

1999 ANNUAL REPORT

ACT/007/033

Wildcat Loadout

File in:

☐ Confidential

☐ Shelf

☒ Expandable

Refer to Record No. 0003 Date 05/01/2000

In C/0070033 3000 Incoming

For additional information

GENERAL INFORMATION

1. Permit Number	ACT 007/033		
2. Mine Name	Wildcat Loadout		
3. Permittee Name	ANDALEX Resources, Inc.		
4. Operator Name (if other than Permittee)	Same		
5. Permit Expiration Date	May, 2004		
6. Company Representative, Title	Michael W. Glasson, Senior Geologist		
7. Phone Number	(435) 637-5385		
8. Fax Number	(435) 637-8860		
9. Mailing Address	P.O. Box 902		
	Price, Utah		
	84501		
10. Resident Agent, Title	Michael W. Glasson, Resident Agent		<div style="font-size: 2em; font-weight: bold; margin-bottom: 10px;">RECEIVED</div> <div style="font-size: 1.2em; font-weight: bold; margin-bottom: 10px;">MAY 04 2000</div> <div style="font-size: 1.2em; font-weight: bold;">DIVISION OF OIL, GAS AND MINING</div>
Mailing Address	Same		

IDENTIFICATION OF OTHER PERMITS

Identify other permits which are required in conjunction with mining and reclamation activities.

Permit Type	ID Number	Description	Expires on
1. MSHA Mine ID(s)	42-01864	Wildcat Unit-Train Loadout	N/A
2. MSHA Impoundment(s)	No		
3. NPDES/UPDES Permit(s) (water)	UTG04000 7	Sediment Pond Discharge (6 each)	April 30, 2003
4. PSD (Air) Permit(s)	DEQ	Air Quality Approval Order	N/A

1999 ANNUAL REPORT	Wildcat Loadout	ACT 007/033	Page 2
5.			
6.			

CERTIFIED REPORTS

List the certified inspection reports as required by the rules and under the approved plan which must be periodically submitted to the Division. Specify whether the information is included as APPENDIX A to this Annual Report or currently ON FILE with the Division.

Certified Reports:	Reports Required?		INCLUDED or ON FILE w/DOGM?			Comments
	YES	NO	YES	NO	ON FILE	
1. Excess Spoil Piles		XX		XX		
2. Refuse Piles	XX		XX			
3. Impoundments	XX		XX			
4.						
5.						

REPORTING OF OTHER TECHNICAL DATA

List other technical data and information as required under the approved plan which must be periodically submitted to the Division. Specify whether the information is included as APPENDIX B to this Annual Report or currently ON FILE with the Division.

Technical Data:	Reports Required?		INCLUDED or ON FILE w/DOGM?			Comments
	YES	NO	YES	NO	ON FILE	
1. Climatological Data		XX		XX		
2. Subsidence Monitoring Data		XX		XX		
3. Vegetation Monitoring Data		XX		XX		
4. Raptor Data		XX		XX		
5. Soils Monitoring Data		XX		XX		
6. Water Monitoring Data	XX		XX			
First Quarter Report	XX		XX			
Second Quarter Report	XX		XX			
Third Quarter Report	XX		XX			
Fourth Quarter Report	XX		XX			
7. Geological/Geophysical Data		XX		XX		
8. Engineering Data		XX		XX		
9. Other Data						

APPENDIX A

Certified Reports

Excess Spoil Piles
Refuse Piles
Impoundments

as required under R645-301-514

CONTENTS

Refuse Pile Inspection
Impoundment Inspection

**ANDALEX RESOURCES, INC. - WILDCAT LOADOUT
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01864-01

QUARTER: 01/99

ITEM	REMARKS
(1) Potential Safety Hazards	<i>None Noted.</i>
(2) Slope Stability	<i>Slopes appear stable.</i>
(3) Removal of Topsoil/Organics.	<i>N/A - No new removal necessary.</i>
(4) Construction and Maintenance Performance Standards.	<i>Pile graded. Sign - O.K. Ditches - O.K.</i>
(5) Recommendations/Comments.	<i>None.</i>

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.



Dan W. Guy
(Signature)

03/10/99
(Date)

**ANDALEX RESOURCES, INC. - WILDCAT LOADOUT
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01864-01

QUARTER: 02/99

ITEM	REMARKS
(1) Potential Safety Hazards	<i>None Noted.</i>
(2) Slope Stability	<i>Slopes appear stable.</i>
(3) Removal of Topsoil/Organics.	<i>N/A - No new removal necessary.</i>
(4) Construction and Maintenance Performance Standards.	<i>Pile graded. Sign - O.K. Ditches - O.K.</i>
(5) Recommendations/Comments.	<i>None.</i>

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.




(Signature)

05/22/99
(Date)

**ANDALEX RESOURCES, INC. - WILDCAT LOADOUT
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01864-01 **QUARTER:** 03/99

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Slopes disrupted.
(3) Removal of Topsoil/Organics	Regrading Pile.
(4) Construction and Maintenance Performance Standards	Working on Pile. Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Recheck when work completed.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.




(Signature)

08/06/99
(Date)

**ANDALEX RESOURCES, INC. - WILDCAT LOADOUT
REFUSE PILE INSPECTION REPORT**

MSHA SITE: 1211-UT-09-01864-01 **QUARTER:** 04/99

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Slopes disrupted.
(3) Removal of Topsoil/Organics	Regrading Pile.
(4) Construction and Maintenance Performance Standards	Working on Pile. Sign - O.K. Ditches - O.K.
(5) Recommendations/Comments	Recheck when work completed.

I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.




(Signature)

10/12/99
(Date)

ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Permanent Impoundment **LOCATION:** Wildcat

IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	0.370 acre feet. (Upper) 0.530 acre feet. (Lower)
(6) Monitoring Procedures	Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	N/A
(8) Sediment Cleanout Level (Elevation)	N/A
(9) Principle Spillway (Elevation)	N/A
(10) Emergency Spillway (Elevation)	N/A
(11) Existing Sediment Capacity (To Cleanout)	N/A

GENERAL	
(12) Comments/Recommendations	Reconstructed in 10/91. Permanent Impoundment. No Discharge.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Depression Area **LOCATION:** Wildcat

IMPOUNDMENTS	
(1) Stability	Railroad Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	N/A - Some coal in area.
(6) Monitoring Procedures	Monitor for water depth for pumping.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	N/A
(8) Sediment Cleanout Level (Elevation)	N/A
(9) Principle Spillway (Elevation)	N/A
(10) Emergency Spillway (Elevation)	N/A
(11) Existing Sediment Capacity (To Cleanout)	N/A

GENERAL	
(12) Comments/Recommendations	Depression area next to railroad. Full of coal stockpile.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



APPENDIX B


Reporting of Technical Data

including monitoring data, reports, maps, and other information
as required under the approved plan
or as required by the Division

in accordance with the requirements of R645-301-130 and R645-301-140.

CONTENTS

Quarterly Water Monitoring
Sedimentation Pond Inspection



ANDALEX
RESOURCES, INC.

P.O. BOX 902
PRICE, UTAH 84501
PHONE (435) 637-5385
FAX (435) 637-8860


MEMORANDUM

TO: DOGM, General Inspection File
FROM: Michael W. Glasson *MWG*
DATE: April 12, 1999
SUBJECT: 1999 1st Quarter Water Monitoring, Wildcat

Water Monitoring- 1st Quarter, 1999
January 1 to March 31, 1999

WCW-1	No Flow 3/31/99
WCW-2	No Flow 3/31/99
WCW-3	No Flow 3/31/99
WCW-4	No Flow 3/31/99

cc: Jim Smith, DOGM
File



ANDALEX
RESOURCES, INC.

P.O. BOX 902
PRICE, UTAH 84501
PHONE (435) 637-5385
FAX (435) 637-8860

MEMORANDUM


TO: DOGM, General Inspection File
FROM: Michael W. Glasson *MWG*
DATE: July 8, 1999
SUBJECT: 1999 2nd Quarter Water Monitoring - Wildcat

Water Monitoring - 2nd quarter, 1999

April 1 to June 30, 1999

WCW-1	No Flow 06/30/99
WCW-2	No Flow 06/30/99
WCW-3	No Flow 06/30/99
WCW-4	No Flow 06/30/99

cc: Jim Smith, DOGM
File



ANDALEX
RESOURCES, INC.

P.O. BOX 902
PRICE, UTAH 84501
PHONE (435) 637-5385
FAX (435) 637-8860


MEMORANDUM

TO: DOGM, General Inspection File
FROM: Michael W. Glasson *MWG*
DATE: October 7, 1999
SUBJECT: 1999 3rd Quarter Water Monitoring, Wildcat

Water Monitoring- 3rd Quarter, 1999
July 1 to September 30, 1999

WCW-1	No Flow 9/30/99
WCW-2	No Flow 9/30/99
WCW-3	No Flow 9/30/99
WCW-4	No Flow 9/30/99

cc: Jim Smith, DOGM
File



ANDALEX
RESOURCES, INC.

P.O. BOX 902
PRICE, UTAH 84501
PHONE (435) 637-5385
FAX (435) 637-8860

MEMORANDUM

TO: DOGM, General Inspection File
FROM: Michael W. Glasson
DATE: January 10, 2000
SUBJECT: 1999 4th Quarter Water Monitoring, Wildcat

Water Monitoring- 4th Quarter, 1999
October 1 to December 31, 1999

WCW-1	No Flow 12/30/99
WCW-2	No Flow 12/30/99
WCW-3	No Flow 12/30/99
WCW-4	No Flow 12/30/99

cc: Jim Smith, DOGM
File

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "A"

DATE: 03/10/99

Inlet & Outlet Conditions:	O.K. - Culverts/Ditches open.
Erosion Problems:	Minor undercutting under belting.
Embankment Stability:	Stable - Mostly Incised.
Water Level:	Dry.
Weather Conditions:	Clear/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection:

11:51 a.m.

Person Conducting Inspection:

Dan W. Guy



*Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report*

POND: Sediment Pond "B"

DATE: 03/10/99

<i>Inlet & Outlet Conditions:</i>	<i>Inlet partially full of coal dust.</i>
<i>Erosion Problems:</i>	<i>None Noted.</i>
<i>Embankment Stability:</i>	<i>Stable - Mostly Incised.</i>
<i>Water Level:</i>	<i>Dry.</i>
<i>Weather Conditions:</i>	<i>Clear/Warm.</i>
<i>Additional Comments:</i>	<i>Sign - O.K. Pond has been cleaned.</i>

Time of Inspection:

11:55 a.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "C"

DATE: 03/10/99

Inlet & Outlet Conditions:	O.K. - Culverts/Ditches open.
Erosion Problems:	None Noted.
Embankment Stability:	Stable - Incised.
Water Level:	Damp.
Weather Conditions:	Clear/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection:

12:00 p.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "E"

DATE: 03/10/99

Inlet & Outlet Conditions:	O.K. - Culverts/Outlets open.
Erosion Problems:	Minor erosion on south side.
Embankment Stability:	O.K. - Stable.
Water Level:	Dry.
Weather Conditions:	Clear/Warm.
Additional Comments:	Sign - O.K. Sediment Marker - O.K.

Time of Inspection:

12:10 p.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "D"

DATE: 03/10/99

Inlet & Outlet Conditions:	O.K.
Erosion Problems:	Minor erosion on west side.
Embankment Stability:	Stable - Incised.
Water Level:	Dry.
Weather Conditions:	Clear/Warm.
Additional Comments:	Sign - Down.

Time of Inspection:

12:05 p.m.

Person Conducting Inspection:

Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "F"

DATE: 03/10/99

Inlet & Outlet Conditions:	O.K. - Repaired.
Erosion Problems:	None Noted.
Embankment Stability:	O.K. - Stable.
Water Level:	Dry.
Weather Conditions:	Clear/Warm.
Additional Comments:	Sign - O.K. Sediment Marker - O.K.

Time of Inspection:

12:20 p.m.

Person Conducting Inspection:

Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Permanent Impoundment

DATE: 03/10/99

Inlet & Outlet Conditions:	O.K. - Culverts/Channels open.
Erosion Problems:	None Noted.
Embankment Stability:	O.K. - Stable.
Water Level:	Dry.
Weather Conditions:	Clear/Warm.
Additional Comments:	Not a sediment pond.

Time of Inspection:

12:15 p.m.

Person Conducting Inspection:

Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Depression Area

DATE: 03/10/99

Inlet & Outlet Conditions:	N/A
Erosion Problems:	None Noted.
Embankment Stability:	O.K. - Railroad embankment.
Water Level:	Dry.
Weather Conditions:	Clear/Warm.
Additional Comments:	Not a sediment pond.

Time of Inspection:

12:15 p.m.

Person Conducting Inspection:

Dan W. Guy



*Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report*

POND: Sediment Pond "A"

DATE: 05/22/99

Inlet & Outlet Conditions:	O.K. - Culverts/Ditches open.
Erosion Problems:	Minor undercutting under belting.
Embankment Stability:	Stable - Mostly Incised.
Water Level:	Dry.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection:

12:30 p.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "B"

DATE: 05/22/99

Inlet & Outlet Conditions:	Inlet partially full of coal dust.
Erosion Problems:	None Noted.
Embankment Stability:	Stable - Mostly Incised.
Water Level:	Damp.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection:

12:25 p.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "C"

DATE: 05/22/99

Inlet & Outlet Conditions:	O.K. - Culverts/Ditches open.
Erosion Problems:	None Noted.
Embankment Stability:	Stable - Incised.
Water Level:	Dry.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection: 12:22 p.m.

Person Conducting Inspection: Dan W. Guy 

*Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report*

POND: Sediment Pond "D"

DATE: 05/22/99

<i>Inlet & Outlet Conditions:</i>	<i>O.K.</i>
<i>Erosion Problems:</i>	<i>Minor erosion on west side.</i>
<i>Embankment Stability:</i>	<i>Stable - Incised.</i>
<i>Water Level:</i>	<i>Dry.</i>
<i>Weather Conditions:</i>	<i>Cloudy/Warm.</i>
<i>Additional Comments:</i>	<i>Sign - O.K.</i>

Time of Inspection:

12:20 p.m.

Person Conducting Inspection:

Dan W. Guy




Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "E"

DATE: 05/22/99

Inlet & Outlet Conditions:	O.K. - Culverts/Outlets open.
Erosion Problems:	Minor erosion on south side.
Embankment Stability:	O.K. - Stable.
Water Level:	Dry.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K. Sediment Marker - O.K.

Time of Inspection: 12:17 p.m.

Person Conducting Inspection: Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "F"

DATE: 05/22/99

Inlet & Outlet Conditions:	O.K.
Erosion Problems:	Minor (Within Pond).
Embankment Stability:	O.K. - Stable.
Water Level:	Dry.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K. Sediment Marker - O.K.

Time of Inspection:

12:45 p.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Permanent Impoundment

DATE: 05/22/99

Inlet & Outlet Conditions:	O.K. - Culverts/Channels open.
Erosion Problems:	None Noted.
Embankment Stability:	O.K. - Stable.
Water Level:	Dry.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Not a sediment pond.

Time of Inspection:

12:35 p.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Depression Area

DATE: 05/22/99

Inlet & Outlet Conditions:	<i>N/A</i>
Erosion Problems:	<i>None Noted.</i>
Embankment Stability:	<i>O.K. - Railroad embankment.</i>
Water Level:	<i>Dry.</i>
Weather Conditions:	<i>Cloudy/Warm.</i>
Additional Comments:	<i>Not a sediment pond.</i>

Time of Inspection:

12:40 p.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "A"

DATE: 08/06/99

Inlet & Outlet Conditions:	O.K. - Culverts/Ditches open.
Erosion Problems:	Minor undercutting under belting.
Embankment Stability:	Stable - Mostly Incised.
Water Level:	Damp.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection:

11:25 a.m.

Person Conducting Inspection:

Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "B"

DATE: 08/06/99

Inlet & Outlet Conditions:	Inlet partially full of coal dust.
Erosion Problems:	None Noted.
Embankment Stability:	Stable - Mostly Incised.
Water Level:	1' Water.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection:

11:20 a.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "C"

DATE: 08/06/99

Inlet & Outlet Conditions:	O.K. - Culverts/Ditches open.
Erosion Problems:	None Noted.
Embankment Stability:	Stable - Incised.
Water Level:	3" Water.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection: 11:11 a.m.

Person Conducting Inspection: Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "D"

DATE: 08/06/99

Inlet & Outlet Conditions:	O.K.
Erosion Problems:	Minor erosion on west side.
Embankment Stability:	Stable - Incised.
Water Level:	6" Water.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K.

Time of Inspection: 11:05 a.m.

Person Conducting Inspection: Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "E"

DATE: 08/06/99

Inlet & Outlet Conditions:	O.K. - Culverts/Outlets open.
Erosion Problems:	Minor erosion on south side.
Embankment Stability:	O.K. - Stable.
Water Level:	Damp.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K. Sediment Marker - O.K.

Time of Inspection: 11:00 a.m.

Person Conducting Inspection: Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Sediment Pond "F"

DATE: 08/06/99

Inlet & Outlet Conditions:	O.K.
Erosion Problems:	Minor (Within Pond).
Embankment Stability:	O.K. - Stable.
Water Level:	3" Water.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Sign - O.K. Sediment Marker - O.K.

Time of Inspection:

11:35 a.m.

Person Conducting Inspection:

Dan W. Guy 

Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Permanent Impoundment

DATE: 08/06/99

Inlet & Outlet Conditions:	O.K. - Culverts/Channels open.
Erosion Problems:	None Noted.
Embankment Stability:	O.K. - Stable.
Water Level:	Dry.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Not a sediment pond.

Time of Inspection:

11:35 a.m.

Person Conducting Inspection:

Dan W. Guy



Andalex Resources, Inc.
Wildcat Loadout
Sedimentation Pond Inspection Report

POND: Depression Area

DATE: 08/06/99

Inlet & Outlet Conditions:	N/A
Erosion Problems:	None Noted.
Embankment Stability:	O.K. - Railroad embankment.
Water Level:	Damp.
Weather Conditions:	Cloudy/Warm.
Additional Comments:	Not a sediment pond.

Time of Inspection: 11:30 a.m.

Person Conducting Inspection: Dan W. Guy 



BLACKHAWK ENGINEERING, INC.

Rt. 1, Box 146-H5 - Helper, Utah 84526 - Telephone (435) 637-2422

*Mr. Mike Glasson
Andalex Resources, Inc.
P.O. Box 902
Price, Utah 84501*

**Re: Wildcat Loadout
Pond Inspections**

Dear Mike:

The Annual Pond Inspections and Certifications were done on 10/12/99. Since these inspections are done in the 4th Quarter, the Annual Inspection Report should also be used as the 4th Quarter Pond Inspection Report for this site.

If you have any questions, or need any further information, please let me know.

Sincerely,

A handwritten signature in black ink, appearing to read "Dan W. Guy", with a stylized flourish at the end.

**Dan W. Guy
President**

ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "A"

LOCATION: Wildcat

IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Dry.
(5) Existing Storage Capacity	2.308 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	6144.00
(8) Sediment Cleanout Level (Elevation)	6144.00
(9) Principle Spillway (Elevation)	6149.00
(10) Emergency Spillway (Elevation)	6150.00
(11) Existing Sediment Capacity (To Cleanout)	0.030 acre feet.

GENERAL	
(12) Comments/Recommendations	Thick vegetation in bottom. No Discharge.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "B"

LOCATION: Wildcat

IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Dry.
(5) Existing Storage Capacity	0.423 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	6131.70
(8) Sediment Cleanout Level (Elevation)	6135.00
(9) Principle Spillway (Elevation)	6138.00
(10) Emergency Spillway (Elevation)	6139.00
(11) Existing Sediment Capacity (To Cleanout)	0.188 acre feet.

GENERAL	
(12) Comments/Recommendations	Pond dry. No Discharge. Pond Cleaned in 1999.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "C"

LOCATION: Wildcat

IMPOUNDMENTS

(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	4.169 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT PONDS ONLY

(7) Sediment Accumulation (Elevation)	6131.00
(8) Sediment Cleanout Level (Elevation)	6131.50
(9) Principle Spillway (Elevation)	6137.00
(10) Emergency Spillway (Elevation)	6138.00
(11) Existing Sediment Capacity (To Cleanout)	0.045 acre feet.

GENERAL

(12) Comments/Recommendations	No Discharge.
-------------------------------	---------------

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "D"

LOCATION: Wildcat

IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	0.650 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	6134.85
(8) Sediment Cleanout Level (Elevation)	6136.00
(9) Principle Spillway (Elevation)	6139.00
(10) Emergency Spillway (Elevation)	6140.00
(11) Existing Sediment Capacity (To Cleanout)	0.069 acre feet.

GENERAL	
(12) Comments/Recommendations	No Discharge. Pond cleaned in 1999.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "E"

LOCATION: Wildcat

IMPOUNDMENTS	
(1) Stability	<i>Slopes Stable.</i>
(2) Structural Weakness/Erosion	<i>None Noted.</i>
(3) Potential Safety Hazards	<i>None Noted.</i>
(4) Depth of Impounded Water	<i>N/A - Dry.</i>
(5) Existing Storage Capacity	<i>0.797 acre feet.</i>
(6) Monitoring Procedures	<i>U.P.D.E.S. Quarterly Inspection.</i>

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	<i>6141.60</i>
(8) Sediment Cleanout Level (Elevation)	<i>6142.50</i>
(9) Principle Spillway (Elevation)	<i>6145.00</i>
(10) Emergency Spillway (Elevation)	<i>6146.00</i>
(11) Existing Sediment Capacity (To Cleanout)	<i>0.077 acre feet.</i>

GENERAL	
(12) Comments/Recommendations	<i>Moderate vegetation in bottom. No Discharge.</i>

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Sed. Pond "F"

LOCATION: Wildcat

IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	0.691 acre feet.
(6) Monitoring Procedures	U.P.D.E.S. Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	6168.50
(8) Sediment Cleanout Level (Elevation)	6168.75
(9) Principle Spillway (Elevation)	6173.00
(10) Emergency Spillway (Elevation)	6174.00
(11) Existing Sediment Capacity (To Cleanout)	0.010 acre feet.

GENERAL	
(12) Comments/Recommendations	No Discharge. Inlets repaired.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Permanent Impoundment **LOCATION:** Wildcat

IMPOUNDMENTS	
(1) Stability	Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	0.370 acre feet. (Upper) 0.530 acre feet. (Lower)
(6) Monitoring Procedures	Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	N/A
(8) Sediment Cleanout Level (Elevation)	N/A
(9) Principle Spillway (Elevation)	N/A
(10) Emergency Spillway (Elevation)	N/A
(11) Existing Sediment Capacity (To Cleanout)	N/A

GENERAL	
(12) Comments/Recommendations	Reconstructed in 10/91. Permanent Impoundment. No Discharge.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



ANDALEX RESOURCES, INC.
1999 ANNUAL POND INSPECTION REPORT

POND: Depression Area **LOCATION:** Wildcat

IMPOUNDMENTS	
(1) Stability	Railroad Slopes Stable.
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	N/A - Dry.
(5) Existing Storage Capacity	N/A - Some coal in area.
(6) Monitoring Procedures	Monitor for water depth for pumping.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	N/A
(8) Sediment Cleanout Level (Elevation)	N/A
(9) Principle Spillway (Elevation)	N/A
(10) Emergency Spillway (Elevation)	N/A
(11) Existing Sediment Capacity (To Cleanout)	N/A

GENERAL	
(12) Comments/Recommendations	Depression area next to railroad. Full of coal stockpile.

STATEMENT

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


(Signature)

10/12/99
(Date)



APPENDIX C

Legal, Financial, Compliance and Related Information

Annual Report of Officers

as submitted to the Utah Department of Commerce

and other changes in ownership and control information
as required under R645-301-110.

CONTENTS

Utah Dep't. Of Commerce Officers

In person: 160 East 300 South, 1st Floor
Salt Lake City, Utah 84111

Fax: (801) 530-6111

Web site: <http://www.commerce.state.ut.us>

PROFIT CORPORATION ANNUAL REPORT

FILED

MAR 23 2000



THIS FORM MUST BE COMPLETED IN FULL All profit corporations must file their annual reports and connections within the month of their anniversary date. Failure to do so will result in Delinquency, Revocation or Involuntary Dissolution of the corporate charter.

CORPORATION FILE # 080962

INCORPORATED OR
QUALIFIED DATE 3 / 79
MONTH YEAR

1. CORPORATE NAME ANDALEX Resources, Inc.
2. REGISTERED AGENT John S. Kirkham
3. REGISTERED OFFICE ADDRESS 201 S. Main Street, Suite 1100
4. CITY, STATE & ZIP Salt Lake City, UT 84111 **UTAH**

WHEN CHANGING THE REGISTERED AGENT THE NEW AGENT MUST SIGN

5. INCORPORATED IN THE STATE AND UNDER THE LAWS OF: Delaware

6. ADDRESS OF THE PRINCIPAL OFFICE IN THE HOME STATE 45 W. 10000 S., Suite 401

Sandy, UT 84070

7. BUSINESS PURPOSE:

DOMESTIC, PROFIT CORPORATIONS ARE REQUIRED TO LIST A CORPORATE OFFICER.

OFFICERS

8. PRESIDENT Douglas H. Smith
- ADDRESS 45 W 10000 S. Ste 401
- CITY Sandy STATE UT ZIP 84070
9. VICE PRESIDENT Samuel C. Quigley
- ADDRESS 45 W 10000 S., Ste. 401
- CITY Sandy STATE UT ZIP 84070
10. SECRETARY John Bradshaw
- ADDRESS 45 W 10000 S., Ste. 401
- CITY Sandy STATE UT ZIP 84070
11. TREASURER _____
- ADDRESS _____
- CITY _____ STATE _____ ZIP _____

ALL DOMESTIC CORPORATIONS MUST LIST THREE (3) DIRECTORS, UNLESS THEY FALL UNDER THE EXCEPTIONS STATED IN SECTION 15-10a-803(1)(b)(i) or (ii).

DIRECTORS

12. DIRECTOR Douglas H. Smith
- ADDRESS 45 W 10000 S., Ste 401
- CITY Sandy STATE UT ZIP 84070
13. DIRECTOR Peter B. Green
- ADDRESS 45 W 10000 S., Ste 401
- CITY Sandy STATE UT ZIP 84070
14. DIRECTOR Ronald C. Beedie
- ADDRESS 45 W 10000 S., Ste 401
- CITY Sandy STATE UT ZIP 84070

Under penalties of perjury and as an authorized officer, I declare that this annual report and, if applicable, the statement change of registered office and/or agent, has been examined by me and is, to the best of my knowledge and belief, true, correct, and complete.

15. BY _____

16. Title or Position _____

17. Date _____

IF THERE ARE NO CHANGES FROM THE PREVIOUS YEAR, AND YOU HAVE ALL CORPORATE REQUIREMENTS FILLED PERTAINING TO OFFICER, AND DIRECTOR INFORMATION YOU MAY COMPLETE THE COUPON BELOW, DETACH IT FROM THIS FORM, AND RETURN IT TO OUR OFFICE WITH YOUR PAYMENT.



APPENDIX E

Other Information

in accordance with the requirements of R645-301 and R645-302.

CONTENTS